

# Materials Manager

---

## Voyager 1202G Scanner Configuration

1. First we need to ensure that the proper suffix is being sent upon a successful scan. The steps below will clear any pre-programmed suffix configuration and replace it with a single carriage return after successful scan.



SUFCA2.

**Clear All Suffixes**



VSUFCR.

**Add CR Suffix  
All Symbologies**

2. Next, we need to set the minimum number of characters the scanner will accept for a successful scan. This is important for single digit codes like Technician ID's. Scan these codes in order to complete.



128MIN.

**Minimum Message Length**



K1K

**1**



MNUSAV.

**Save**

3. It is important when printing this page that page scaling be turned off, allowing the page to print in actual size. Codes may not be readable by the scanner if the codes are scaled down.